US ERA ARCHIVE DOCUMENT



Response Management Associates, Inc. (RMA)
President
281-320-9796
www.rmaworld.com

Presented by Response Management Associates

The P.E.'s Perspective

40 CFR Part 112
Spill Prevention,
Control and Countermeasure
(SPCC) Plan

Presented by:
Eric G. Politte, P.E.
Response Management Associates, Inc. (RMA)
President
281-320-9796
www.rmaworld.com

Presented by Response Management Associates

What?

- Rule Dates
- Professional Engineer Certification Review
- Keep it in the container
- Keep it in containment
- Keep it at the Facility
- PERFORMANCE BASED

- January 10, 1974 First Effective Date
- October 22, 1991 Proposed Amendments
- 1993, 1997....

- July 17, 2002 Final Rule Published
- August 16, 2002 1st Effective Date
- February 17, 2003 1st Plan Amendment
- August 18, 2003 1st Plan Implementation

- April 17, 2003 Extension Published
- August 17, 2004 2nd Plan Amendment
- February 18, 2005 − 2nd Plan Implementation

- August 11, 2004 Extension Published
- February 17, 2006 3rd Plan Amendment
- August 18, 2006 3rd Plan Implementation

- February 17, 2006 Extension Published
- October 31, 2007 4th Plan Amendment
- October 31, 2007 4th Plan Implementation

- December, 2005 Proposed Revision
- October 2006 Anticipated Final Revision

Dates of Rule Activity – Target Practice

- 1973 Originally Proposed
- January 10, 1974 First Effective Date
- October 22, 1991 Proposed Amendments
 - July 17, 2002 Final Rule Published
 - August 16, 2002 1st Effective Date
 - February 17, 2003 1st Plan Amendment
- August 18, 2003 1st Plan Implementation
 - April 17, 2003 Extension Published
 - August 17, 2004 2nd Plan Amendment
- February 18, 2005 2nd Plan Implementation
 - August 11, 2004 Extension Published
 - February 17, 2006 3rd Plan Amendment
 - August 18, 2006 3rd Plan Implementation
 - February 17, 2006 Extension Published
 - October 31, 2007 4th Plan Amendment
 - October 31, 2007 4th Plan Implementation
 - December 2005 Proposed Revision
 - October 2006 Anticipated Final Revision

What's the Point?

- Extensions Necessary and Appreciated.
- Many Operators completed new SPCC Plans along the way.
- Many Operators and many P.E.s are responsible for many Plans.
- Consider the review and certification date when reviewing a Plan.
- Immediate reaction to new interpretations and guidance is not practical.
- Bottom Line → PERFORMANCE BASED

By certification, the PE attests that:

- 1. He is familiar with the requirements of the SPCC rule;
- 2. He or his agent has visited and examined the facility;
- 3. The Plan has been prepared in accordance with good engineering practice, including consideration of applicable industry standards, and with the requirements of the SPCC rule;
- 4. Procedures for required inspections and testing have been established; and
- 5. The Plan is adequate for the facility.

Presented by Response Management Associates

- 1. He is familiar with the requirements of the SPCC rule;
- 2. He or his agent has visited and examined the facility;
- 3. The Plan has been prepared in accordance with good engineering practice, including consideration of applicable industry standards, and with the requirements of the SPCC rule;
- 4. Procedures for required inspections and testing have been established; and
- 5. The Plan is adequate for the facility.

- 1. He is familiar with the requirements of the SPCC rule;
- 2. He or his agent has visited and examined the facility;
- 3. The Plan has been prepared in accordance with good engineering practice, including consideration of applicable industry standards, and with the requirements of the SPCC rule;
- 4. Procedures for required inspections and testing have been established; and
- 5. The Plan is adequate for the facility.

- 1. He is familiar with the requirements of the SPCC rule;
- 2. He or his agent has visited and examined the facility;
- 3. The Plan has been prepared in accordance with good engineering practice, including consideration of applicable industry standards, and with the requirements of the SPCC rule;
- 4. Procedures for required inspections and testing have been established; and
- 5. The Plan is adequate for the facility.

- 1. He is familiar with the requirements of the SPCC rule;
- 2. He or his agent has visited and examined the facility;
- 3. The Plan has been prepared in accordance with good engineering practice, including consideration of applicable industry standards, and with the requirements of the SPCC rule;
- 4. Procedures for required inspections and testing have been established; and
- 5. The Plan is adequate for the facility.

- 1. He is familiar with the requirements of the SPCC rule;
- 2. He or his agent has visited and examined the facility;
- 3. The Plan has been prepared in accordance with good engineering practice, including consideration of applicable industry standards, and with the requirements of the SPCC rule;
- 4. Procedures for required inspections and testing have been established; and
- 5. The Plan is adequate for the facility.

PERFORMANCE BASED

Presented by Response Management Associates

 Keep it in the container Keep it in containment Keep it at the Facility


Presented by Response Management Associates

Keep it in the Container → **Integrity Testing, Inspections**

- [112.8] <u>Test</u> each aboveground container for integrity on a regular schedule, and when material repairs are done;
- Take into account container size and design when deciding test frequency and type;
- Must Combine visual inspection with another testing technique (such as hydrostatic, radiographic, ultrasonic, etc.).

Keep it in the Container → Integrity Testing, Inspections

- API 653 (field erected)
- STI SP-001 (shop built)
- API 2350 (overfill protect)
- API 570 (piping)
- NFPA 30
- API 12R1 (E&P)
- Industry Standards+++




Industry Standards

- Over 100 Standards
- Avg 100 pgs each & 10 external references each
- 10,000 pages and 1,000 additional references
- Adopt your CRITICAL FEW reference standards

Keep it in the Container → Integrity Testing, Inspections

CRITICAL FEW

- API 653 (field erected)
- STI SP-001 (shop built)
- API 2350 (overfill protect)
- API 570 (piping)
- NFPA 30
- API 12R1 (E&P)
- PERFORMANCE BASED



 Keep it in the container Keep it in containment Keep it at the Facility **Presented by Response Management Associates**

- How much is enough the Great Debate
- [112.7] Provide appropriate containment...constructed so that discharge...will not escape before clean up...
- [112.8] ...secondary containment for the entire capacity of the largest single container and sufficient freeboard to contain precipitation

How much is enough?

• 110%?

25 year / 24 hr storm event?

1 year / 1/2 hr storm event?



 110% has significant industry support (historical rule of thumb); Utilized as example in D-16; Referenced in EPA Outreach documents; Utilized in many state rules.

• $110\% > 25 / 24 \leftarrow ? \rightarrow 110\% < 25 / 24$

- Point → Allowance for Precipitation.
- Both measures are arbitrary;
- Design for the specific application;
- Document assumptions and calculations.
- PERFORMANCE BASED

- Pre-1974 Facilities (no rule).
- Pre-2002 Facilities (should).
- Good Engineering Judgment often involves the study of Probability/Statistics. How many full volume tank releases have occurred simultaneous with 25 year storm events? How many times has 110% been adequate; been inadequate?
- Performance Based



 Keep it in the container Keep it in containment Keep it at the Facility **Presented by Response Management Associates**

Keep it at the Facility → Sufficiently Impervious

[112.7] The walls and floor of the containment must be capable of containing oil and must be constructed so that any discharge from a tank or pipe will <u>not</u> escape containment before cleanup occurs.



[112.8] ...must ensure that diked areas are <u>sufficiently</u> <u>impervious to contain discharged oil</u>.

Keep it at the Facility → **Sufficiently**Impervious

- What's the issue? Floor permeability.
- Facilities built upon native soils.
- Permeability may be an issue.
- Pre-1974 Facilities (No Rule).
- Pre-2002 Facilities (Should).

Keep it at the Facility → **Sufficiently**Impervious

- After the Fact Installation of Liners is not feasible
- Expect and Accept Utilization of Impracticability
- Keep in mind that containment (for SPCC purposes) is to keep product from reaching navigable water until clean up occurs.

Presented by Response Management Associates


Keep it at the Facility → **Sufficiently**Impervious



Keep it at the Facility → Sufficiently Impervious

- Draw the Black Box 2D
- Keep it in the Box 2D
- Analyze potential 3D conduits
- Tiered Approach
- Utilize Monitoring Wells and Automated Detection

Sufficiently Impervious → Keep it on the Facility



Impracticability

Old rule

 When it is not practicable to install secondary containment at a facility, the owner/operator must explain why and provide a strong spill contingency plan (per 40 CFR 109) describing commitment of manpower, equipment, and materials to control and remove any harmful quantity of oil discharged.

Revised rule

 The owner/operator also must conduct periodic integrity testing of the containers; and conduct periodic integrity and leak testing of the valves and piping.

ReCap

• PERFORMANCE BASED

Keep it in the Container

Keep it in Containment

Keep it at the Facility

Observations (EGP's)

- Guidance Doc great work effort but remember it is Guidance. Rule and SPCC Plans remain Performance Based.
- Applause for the attempt to Standardize across the regions. Uniqueness across regions is understood -- BUT-- compliance with a consistent set of expectations much easier and more effective.

API Update

- Guidance Document -- Substantial comments made, look forward to EPA's acknowledgment and response
- D16 will be revised when EPA finalizes Proposed Rule
- D16 -- would appreciate EPA's review and comments



Contact us for additional information or to discuss our SPCC development capabilities:

281-320-9796
egpolitte@rmaworld.com
www.rmaworld.com

Presented by Response Management Associates